

Certificate

Quality Management system

Envirex Group

Robotveien 16,
4340 Bryne

And locations as listed in attachment in page 2 are found in accordance with

NS-EN 9001:2015

The certification covers the following activities:

Envirex Group supplies products and services within hydraulic systems, mechanical design and control systems to onshore and offshore industry. The service includes design and development of systems, together with project operations and lease of equipment.

Sertifikat nr.:

18-026

Initial certification date: 11.01.2019

Last issued: 10.01.2022

Valid to: 11.01.2025

Annual follow-up



General Manager



Board Chairman

VERIFY

Vassbotnen 15, 4313 Sandnes



Attachment to Certificate

This attachment refers to certificate number 18-026

Envirex Group

Companies included in the certification are as follows:

Envirex AS, Robotvegen 16, 4340 Bryne

Fully integrated supplier within hydraulic and mechanical design, production and offshore operations. The company has resources within engineering, project management and industrial personnel, enabling one stop shop for complex deliveries, primarily for the oil and gas industry.

iCsys AS, Postvegen 610, 4351 Klepp Stasjon

Wholly owned software and hardware for integrated control systems. The company designs and develops its own systems to use for a wide range of applications. The systems is provided for a variety of projects in onshore industry, subsea and space.

Envirent AS, Robotvegen 16, 4340 Bryne

Rental of machines and tooling, primarily to the subsea industry. A broad product range enables the company to be a fully integrated supplier for its customer base. The company may also supply resources from the Envirex Group to include personnel and control systems for project deliveries to the onshore and offshore industry.

Initial Certification date:

11.01.2019

Last issued:

10.01.2022

Certificate valid to:


11.01.2025

Place and date:

Sandnes, 10.01.2022



General Manager



Board Chairman

Failure to fulfill the terms set out in the certification agreement may result in the certificate being invalidated.

VERIFY

Vassbotnen 15, 4313 Sandnes

